GRINER

GRINER DRILLING SERVICE Inc.
COLUMBIA, MISSISSIPPI
(601) 736-6347

DEC 13 1993

SP,16,64 & GAMMA #228

COMPANY: ROMOLA WATER ASSN.
WELL: TEST HOLE # 1 635
FIELD: CLAIRBORNE MS.

LOCATION: SECTION: 45
TOWNSHIP: 12 NORTH
RANGE: 3 EAST

OTHER LOGS:

PERM. DATUM: ROTARY LEVEL
ELEVATION: N/A
LOG MEASURED FROM: ROTARY LEVEL

DATE:	05 NOV. 1993			
RUN NUMBER:	ONE			
DRILLER:				
DEPTH at BIT DIA.	609 FT.			
DEPTH at BIT DIA.				
CASING DPTH/SIZE	0 FT.			
CASING DPTH/SIZE	0 FT.			
LOGGER:				
DEPTH	609 FT.			
CASING DEPTH	0 FT.			
BOT LOG INTERVAL	609 FT.			
TOP LOG INTERVAL	50 FT.			
TYPE FLUID IN HOLE	WATER BASED			
Rm at TEMP				
SAMPLE SOURCE	MUD PIT			
FLUID LVL/CIRC.	SURFACE			
TIME SINCE CIRC.STOP.				
RECORDED BY:	MIKE GRINER			
OBSERVER:	JERRY BEACH			

RUN #	ONE
PROBE TYPE / S.N.	SP,16,64 & GAMMA
MODULE TYPE / S.N.	SP,16,64 & GAMMA
LOGGING SPEED	30 ft./minute
AFTER SURVEY DEPTH ERROR	
SAMPLE INTERVAL =	

COMMENTS: